

TJ Scott Family Investments LLC

29982 Country Club Drive
Costa Mesa, CA 92626
Phone: 562-843-7570 Fax: [Your Fax]
E-Mail: tomscott@4dd.net
Web:

7/26/2017

Los Angeles Regional Water Quality Control Board
Attn: Joshua Cwikla

320 W. Fourth Street, Suite 200
Los Angeles, CA 90013

Dear Joshua:

Our only well, Fee#1, located at 3329 Linden Ave (33.817835,-118.186400) does not have a sump. All our waste water is processed by Oil Operators via a clarifier.

There is no current nor historic sump at our location. We have no procedure for closing sumps as we have no sumps. No annual fluid is discharged into the land via a sump at all, so no fluid composition, nor solids are dumped into any sump at our location. I have no knowledge of any water wells within a half mile of our well commercial or otherwise. Nor is there any known historic water well in the same radius. No sampling of well water due to no wells in the area, and no survey data since there are no wells to survey.

Oil Operators handles the treatment of our waste water and we report the oil and water numbers via DOGGR. The average water treated by Oil Operators for us is 18,000 barrels annually if the well were operational every day.

I, Tom Scott certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of the those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

Sincerely,



Tom Scott
Owner/Operator